



An ISO 9001:2008 Registered Company

Technical Service Bulletin

TSB # T2011-01 10/12/11

Product: All products manufactured by InterMotive Vehicle Controls that connect to the OBD II plug that will be installed on 2012 chassis.

Vehicle: N/A.

Issue: Many products from InterMotive require a CAN Bus connection and read the VIN. Therefore, current part numbers may remain the same but will require an update to add the 2012 model year VINs to the module's firmware.

Please check product prior to installation on a 2012 chassis to ensure that the module firmware is at least the version listed below (e.g. installation of a GTWY505 on a 2012 Econoline should be 2.12 or higher).

Action: This TSB provides a list, by part number, of the firmware level that added the 2012 VINs.

Additional information: If you have 2011 model year product (built on our new mini or micro platforms) in inventory you may be able to update the firmware to the latest level by using a GUI programming cable. Contact InterMotive for details.

Firmware Needed for 2012 Updates	
<i>Part Number</i>	<i>Firmware #</i>
AFIS420/422VSX-B	2.03
AFIS506/507VSX-B	2.02
AFIS511VSX	2.00
CVC501/502	2.11
ECO501	2.06
EMS501	2.10
GTWY505	2.12
GTWY506	2.11
GTWY605	2.11
GTWY805	2.02
HL510	2.12
HL550	2.11
HL610	2.11
ILISC301	2.00
ILISC510	2.00
ILISC610	2.01
ILISC805	2.02
ILISCT511	1.02
ILISP510	2.00
ILISP610	2.01
ITC502	2.11
ITC520	2.01
ITC620	2.01
J1939XR501-A	2.01
LOCK510	2.00
LOCK610	2.01
NFPA501/502/506	2.01
WTSI506	2.11
WTSI606	2.01

Technical inquiries – InterMotive Technical Support (530) 823-1048